

# **Vetrosmart**

Solution of high repellency to water and other substances for glass (indoor and outdoor static glass )

Shower screens, windows, mirrors or other glass surfaces

### SHOWER SCREENS, WINDOWS AND MIRRORS ALWAYS CLEAN!



Product with properties of high repellency to water and other substances:

- It creates a protective film that repels liquids, facilitating their removal from the treated glass.
- It avoids lime and dirt accumulation facilitating its removal by the drag action of water.
- It is a surface treatment for glass that protects and minimizes dirt and lime scale deposits.

## Vetrosmart

### PROPERTIES

EASY CLEANING, it reduces cleaning times substantially.

**KEEP SURFACES CLEAN FOR A LONGER TIME**, maintaining the original appearance.

HIGH PRODUCT DURABILITY, Up to 3 years or up to 10 years for professional application in new glass.

EASY APPLICATION PRODUCT, without the necessity of special safety measures.

HIGH FEATURES AND HIGH PERFORMANCE: 50-60 m<sup>2</sup>/L.

**ULTRA-FAST DRYING AFTER THE TREATMENT,** avoiding cumbersome spots on further handling.

**AFTER APPLICATION**, the coating results totally transparent, not modifying at all the aesthetic conditions of the glass.

## Your glasses ready in a minute!





## **Vetrosmart**

### **HOW TO USE**

- Before each use, shake the container vigorously.
- The surface must be clean and dry, without any posible lime stains, dirt or traces of detergents (depends on surfaces).
- Methods of apliccation:

1– Manual Spray.

• Spread it helping yourself with a paper, microfiber cloth or similar to distribute the product evenly through the area, ensuring that the entire surface is treated.

Important: Avoid the use of cloths that leave fabric traces while used.

• Polish the surface with a dry cloth until removing any visible trace of product, ensuring the glass is totally transparent.

2- Airless.

• Apply the product over the surface homogeneously, or in a single layer of higher amount of product or in two thinner layers.

**Important:** It must appear a wihitish "mottled veil" in the treated surface. (In case of not appear, it can means not enough product).

- Remove the whitish veil with a dry cloth untill totally transparent.
- <u>In both cases is important</u>: to work in áreas of appropriate size to avoid an excessive drying of the product which difficults its removal.

#### **TECNADIS SOLUTIONS - OTHER FINAL USE NANOPRODUCTS**



**TECNOLOGÍA NAVARRA DE NANOPRODUCTOS S.L.** 

Área Industrial Perguita, A Street Nº1

31210 Los Arcos (Navarra) - Spain

Tel.: +34 948 640 318 - Fax: +34 948 640 319



www.tecnan-nanomat.es

tecnan@tecnan-nanomat.es

